

In the Drawing:

As shown in the accompanying marked-up replacement sheet, please amend the drawings as follows.

Figure 5 has been amended to include numeral “114” to identify an interior side wall, numeral “116” to identify an exterior side wall, numeral “132” to identify a top edge, numeral “136” to identify a front edge and numeral “138” to identify a rear edge. Figure 5 has been also amended to clarify a top surface identified as numeral “124.”

Figure 6 has been amended to include numeral “114” to identify an interior side wall.

Figure 7 has been amended to include numeral “116” to identify an exterior side wall, numeral “132” to identify a top edge, numeral “136” to identify a front edge and numeral “138” to identify a rear edge.

Figure 8 has been amended to include numeral “112” to identify a front surface.

Figure 9 has been amended to include numerals “120, 122” to identify a real wall and numeral “118” to identify opening. Figure 9 has been also amended to identify the opening.

Figure 10 has been amended to include numeral “124” to identify a top stanchion surface.

Figure 11 has been amended to include numeral “126” to identify a bottom stanchion surface.

Figures 80B and 81B have been amended to correct numeral “340” to numeral “350” to avoid using the same numeral “340” that also identifies four rectangular brackets.

The changes have been indicated in red and it is not believed to contain new matter.

Attachment: Replacement sheets



Replacement Sheet

FIG. 8




FIG. 9




FIG. 7




FIG. 6




FIG. 10





FIG. 11



120
118
3/36

122

112

120

112

124

122
126

112
118

116

122

138

134

134

126

126

134

138

116

122

136

126

126

134

114
112
118

132

120

112


118

114



Replacement Sheet

FIG. 80A



35/36
FIG. 80B




FIG. 81A




FIG. 81B




FIG. 82A




FIG. 82B

